NOTICE

The Auction Yard strives to give our bidders as much information about the vehicles being auctioned as possible. This is a non binding guess that we provide as a courtesy, There are no doubt latent defects that we are unable to test. You are still required to preview even if you do not live nearby. Due to our Public Auction Dealers License, we are required to sell all vehicles "as-is" "where-is" with all faults. With no Implied Warranty of any kind and no refunds or credit, no exceptions.

2010 Mercedes-Benz E-Class E 350

| Engine | | Acce | Accessories | | Interior | |
|-------------------------------------|--------------|-------------------------------------|--------------------------------------|--------------------------------------|--------------------------------------|--|
| We have visually inspected the | | We have turned on the A/C and | | Visually inspected the interior | | |
| engine for completeness, checked | | heater, rolled all windows up and | | of the vehicle including dash, head | | |
| the oil color and level, drove the | | down, checked th | down, checked the door locks, | | liner, door panels, front seats | |
| vehicle around the yard 3 times, | | turned the radio on and off, and | | back seats, carpet rear of vehicl | | |
| and let the vehicle idle for 3 min. | | checked other pov | checked other power options work. | | and inside of trunk. | |
| No issues noted | See Comments | No issues noted | See Comments | No issues noted | See Comments | |
| x | | Х | | | x | |
| Comments: | | Comments: | | Comments: | | |
| | | | | minor cosmetic | | |
| | | | | | | |
| Transmission | | Service Ligh | Service Lights and Leaks | | Exterior | |
| We have driven the vehicle around | | We have visually inspected the dash | | Visually inspected the exterior of | | |
| the yard 3 times and checked that | | while the vehicles was running for | | the vehicle including bumpers, | | |
| the vehicle goes into <u>second</u> | | any service lights on. We have | | fenders, doors, hood and top for | | |
| gear and reverse. We also | | also visually inspected for any | | dents, major scratches, paint | | |
| checked fluid levels and for leaks. | | evidence of major leaks under car. | | condition, lights and body issues. | | |
| No issues noted | See Comments | No issues noted | See Comments | No issues noted | See Comments | |
| x | | x | | | x | |
| Comments: | | | | | | |
| | | | | minor cosmetic, damage faded | | |
| | | | | paint | | |
| Charging System | | Engine Coo | Engine Cooling System | | Tires | |
| We have turned the vehicle on | | We have visually inspected the | | We have visually inspected all tires | | |
| and off several times, idoled it, | | hoses and radiator for leaks, ran | | on vehicle for depth of tread, | | |
| and have visually inspected the | | the vehicle to temp and checked | | presence of dry rought,air pressure | | |
| battery, cables, and alternator. | | for overheating. C | for overheating. Checked fluid level | | size differences and condition. | |
| | See Comments | | | No issues noted | See Comments | |
| X | | Х | | Х | | |
| Comments: | | Comments: | Comments: | | Comments: | |
| | | | | | | |
| | | | | | | |
| Brakes and Suspension | | Ligh | Lights | | Glass | |
| We have driven the vehicle around | | We have turned on & off the head | | We have inspected all glass on | | |
| the yard three times stopping and | | lights, blinkers, ha | lights, blinkers, hazard lights, and | | vehicle for chips, cracks, tint, and | |
| going and listened for noises. | | • | interior dome lights on vehicle | | general condition issues. | |
| No issues noted | | No issues noted | See Comments | No issues noted | | |
| X | | Х | | X | | |
| Comments: | | Comments: | | Comments: | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |