

## NOTICE

The Auction Yard strives to give our bidders as much information about the vehicles being auctioned as possible. This is a non binding guess that we provide as a courtesy, There are no doubt latent defects that we are unable to test. You are still required to preview even if you do not live nearby. Due to our Public Auction Dealers License, we are required to sell all vehicles "as-is" "where-is" with all faults. With no Implied Warranty of any kind and no refunds or credit, no exceptions.

### 2011 MINI Clubman Cooper

<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th colspan="2" style="text-align: center;">Engine</th> </tr> </thead> <tbody> <tr> <td colspan="2">We have visually inspected the engine for completeness, checked the oil color and level, <b>drove the vehicle around the yard 3 times</b>, and let the vehicle idle for 3 min.</td> </tr> <tr> <td style="text-align: center;"><i>No issues noted</i></td> <td style="text-align: center;"><i>See Comments</i></td> </tr> <tr> <td style="text-align: center;">X</td> <td></td> </tr> <tr> <td colspan="2"><i>Comments:</i></td> </tr> <tr> <td colspan="2"> </td> </tr> </tbody> </table>	Engine		We have visually inspected the engine for completeness, checked the oil color and level, <b>drove the vehicle around the yard 3 times</b> , and let the vehicle idle for 3 min.		<i>No issues noted</i>	<i>See Comments</i>	X		<i>Comments:</i>				<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th colspan="2" style="text-align: center;">Accessories</th> </tr> </thead> <tbody> <tr> <td colspan="2">We have turned on the A/C and heater, rolled all windows up and down, checked the door locks, turned the radio on and off, and checked other power options work.</td> </tr> <tr> <td style="text-align: center;"><i>No issues noted</i></td> <td style="text-align: center;"><i>See Comments</i></td> </tr> <tr> <td style="text-align: center;">X</td> <td></td> </tr> <tr> <td colspan="2"><i>Comments:</i></td> </tr> <tr> <td colspan="2"> </td> </tr> </tbody> </table>	Accessories		We have turned on the A/C and heater, rolled all windows up and down, checked the door locks, turned the radio on and off, and checked other power options work.		<i>No issues noted</i>	<i>See Comments</i>	X		<i>Comments:</i>				<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th colspan="2" style="text-align: center;">Interior</th> </tr> </thead> <tbody> <tr> <td colspan="2">Visually inspected the interior of the vehicle including dash, head liner, door panels, front seats back seats, carpet rear of vehicle and inside of trunk.</td> </tr> <tr> <td style="text-align: center;"><i>No issues noted</i></td> <td style="text-align: center;"><i>See Comments</i></td> </tr> <tr> <td></td> <td style="text-align: center;">X</td> </tr> <tr> <td colspan="2"><i>Comments:</i></td> </tr> <tr> <td colspan="2">minor cosmetic</td> </tr> <tr> <td colspan="2"> </td> </tr> </tbody> </table>	Interior		Visually inspected the interior of the vehicle including dash, head liner, door panels, front seats back seats, carpet rear of vehicle and inside of trunk.		<i>No issues noted</i>	<i>See Comments</i>		X	<i>Comments:</i>		minor cosmetic			
Engine																																								
We have visually inspected the engine for completeness, checked the oil color and level, <b>drove the vehicle around the yard 3 times</b> , and let the vehicle idle for 3 min.																																								
<i>No issues noted</i>	<i>See Comments</i>																																							
X																																								
<i>Comments:</i>																																								
Accessories																																								
We have turned on the A/C and heater, rolled all windows up and down, checked the door locks, turned the radio on and off, and checked other power options work.																																								
<i>No issues noted</i>	<i>See Comments</i>																																							
X																																								
<i>Comments:</i>																																								
Interior																																								
Visually inspected the interior of the vehicle including dash, head liner, door panels, front seats back seats, carpet rear of vehicle and inside of trunk.																																								
<i>No issues noted</i>	<i>See Comments</i>																																							
	X																																							
<i>Comments:</i>																																								
minor cosmetic																																								
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th colspan="2" style="text-align: center;">Transmission</th> </tr> </thead> <tbody> <tr> <td colspan="2">We have driven the vehicle around the yard 3 times and checked that the vehicle goes into <b>second gear and reverse</b>. We also checked fluid levels and for leaks.</td> </tr> <tr> <td style="text-align: center;"><i>No issues noted</i></td> <td style="text-align: center;"><i>See Comments</i></td> </tr> <tr> <td style="text-align: center;">X</td> <td></td> </tr> <tr> <td colspan="2"><i>Comments:</i></td> </tr> <tr> <td colspan="2"> </td> </tr> </tbody> </table>	Transmission		We have driven the vehicle around the yard 3 times and checked that the vehicle goes into <b>second gear and reverse</b> . We also checked fluid levels and for leaks.		<i>No issues noted</i>	<i>See Comments</i>	X		<i>Comments:</i>				<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th colspan="2" style="text-align: center;">Service Lights and Leaks</th> </tr> </thead> <tbody> <tr> <td colspan="2">We have visually inspected the dash while the vehicles was running for any service lights on. We have also visually inspected for any evidence of major leaks under car.</td> </tr> <tr> <td style="text-align: center;"><i>No issues noted</i></td> <td style="text-align: center;"><i>See Comments</i></td> </tr> <tr> <td style="text-align: center;">X</td> <td></td> </tr> <tr> <td colspan="2"><i>Comments:</i></td> </tr> <tr> <td colspan="2"> </td> </tr> </tbody> </table>	Service Lights and Leaks		We have visually inspected the dash while the vehicles was running for any service lights on. We have also visually inspected for any evidence of major leaks under car.		<i>No issues noted</i>	<i>See Comments</i>	X		<i>Comments:</i>				<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th colspan="2" style="text-align: center;">Exterior</th> </tr> </thead> <tbody> <tr> <td colspan="2">Visually inspected the exterior of the vehicle including bumpers, fenders, doors, hood and top for dents, major scratches, paint condition, lights and body issues.</td> </tr> <tr> <td style="text-align: center;"><i>No issues noted</i></td> <td style="text-align: center;"><i>See Comments</i></td> </tr> <tr> <td></td> <td style="text-align: center;">X</td> </tr> <tr> <td colspan="2"><i>Comments:</i></td> </tr> <tr> <td colspan="2">minor cosmetic</td> </tr> <tr> <td colspan="2"> </td> </tr> </tbody> </table>	Exterior		Visually inspected the exterior of the vehicle including bumpers, fenders, doors, hood and top for dents, major scratches, paint condition, lights and body issues.		<i>No issues noted</i>	<i>See Comments</i>		X	<i>Comments:</i>		minor cosmetic			
Transmission																																								
We have driven the vehicle around the yard 3 times and checked that the vehicle goes into <b>second gear and reverse</b> . We also checked fluid levels and for leaks.																																								
<i>No issues noted</i>	<i>See Comments</i>																																							
X																																								
<i>Comments:</i>																																								
Service Lights and Leaks																																								
We have visually inspected the dash while the vehicles was running for any service lights on. We have also visually inspected for any evidence of major leaks under car.																																								
<i>No issues noted</i>	<i>See Comments</i>																																							
X																																								
<i>Comments:</i>																																								
Exterior																																								
Visually inspected the exterior of the vehicle including bumpers, fenders, doors, hood and top for dents, major scratches, paint condition, lights and body issues.																																								
<i>No issues noted</i>	<i>See Comments</i>																																							
	X																																							
<i>Comments:</i>																																								
minor cosmetic																																								
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th colspan="2" style="text-align: center;">Charging System</th> </tr> </thead> <tbody> <tr> <td colspan="2">We have turned the vehicle on and off several times, idoled it, and have visually inspected the battery, cables, and alternator.</td> </tr> <tr> <td></td> <td style="text-align: center;"><i>See Comments</i></td> </tr> <tr> <td></td> <td style="text-align: center;">X</td> </tr> <tr> <td colspan="2"><i>Comments:</i></td> </tr> <tr> <td colspan="2">dead battery</td> </tr> <tr> <td colspan="2"> </td> </tr> </tbody> </table>	Charging System		We have turned the vehicle on and off several times, idoled it, and have visually inspected the battery, cables, and alternator.			<i>See Comments</i>		X	<i>Comments:</i>		dead battery				<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th colspan="2" style="text-align: center;">Engine Cooling System</th> </tr> </thead> <tbody> <tr> <td colspan="2">We have visually inspected the hoses and radiator for leaks, ran the vehicle to temp and checked for overheating. Checked fluid level</td> </tr> <tr> <td style="text-align: center;"><i>No issues noted</i></td> <td style="text-align: center;"><i>See Comments</i></td> </tr> <tr> <td style="text-align: center;">X</td> <td></td> </tr> <tr> <td colspan="2"><i>Comments:</i></td> </tr> <tr> <td colspan="2"> </td> </tr> </tbody> </table>	Engine Cooling System		We have visually inspected the hoses and radiator for leaks, ran the vehicle to temp and checked for overheating. Checked fluid level		<i>No issues noted</i>	<i>See Comments</i>	X		<i>Comments:</i>				<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th colspan="2" style="text-align: center;">Tires</th> </tr> </thead> <tbody> <tr> <td colspan="2">We have visually inspected all tires on vehicle for depth of tread, presence of dry rought, air pressure size differences and condition.</td> </tr> <tr> <td style="text-align: center;"><i>No issues noted</i></td> <td style="text-align: center;"><i>See Comments</i></td> </tr> <tr> <td style="text-align: center;">X</td> <td></td> </tr> <tr> <td colspan="2"><i>Comments:</i></td> </tr> <tr> <td colspan="2"> </td> </tr> </tbody> </table>	Tires		We have visually inspected all tires on vehicle for depth of tread, presence of dry rought, air pressure size differences and condition.		<i>No issues noted</i>	<i>See Comments</i>	X		<i>Comments:</i>			
Charging System																																								
We have turned the vehicle on and off several times, idoled it, and have visually inspected the battery, cables, and alternator.																																								
	<i>See Comments</i>																																							
	X																																							
<i>Comments:</i>																																								
dead battery																																								
Engine Cooling System																																								
We have visually inspected the hoses and radiator for leaks, ran the vehicle to temp and checked for overheating. Checked fluid level																																								
<i>No issues noted</i>	<i>See Comments</i>																																							
X																																								
<i>Comments:</i>																																								
Tires																																								
We have visually inspected all tires on vehicle for depth of tread, presence of dry rought, air pressure size differences and condition.																																								
<i>No issues noted</i>	<i>See Comments</i>																																							
X																																								
<i>Comments:</i>																																								
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th colspan="2" style="text-align: center;">Brakes and Suspension</th> </tr> </thead> <tbody> <tr> <td colspan="2">We have driven the vehicle around the yard three times stopping and going and listened for noises.</td> </tr> <tr> <td style="text-align: center;"><i>No issues noted</i></td> <td style="text-align: center;"><i>See Comments</i></td> </tr> <tr> <td style="text-align: center;">X</td> <td></td> </tr> <tr> <td colspan="2"><i>Comments:</i></td> </tr> <tr> <td colspan="2"> </td> </tr> </tbody> </table>	Brakes and Suspension		We have driven the vehicle around the yard three times stopping and going and listened for noises.		<i>No issues noted</i>	<i>See Comments</i>	X		<i>Comments:</i>				<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th colspan="2" style="text-align: center;">Lights</th> </tr> </thead> <tbody> <tr> <td colspan="2">We have turned on &amp; off the head lights, blinkers, hazard lights, and interior dome lights on vehicle</td> </tr> <tr> <td style="text-align: center;"><i>No issues noted</i></td> <td style="text-align: center;"><i>See Comments</i></td> </tr> <tr> <td style="text-align: center;">X</td> <td></td> </tr> <tr> <td colspan="2"><i>Comments:</i></td> </tr> <tr> <td colspan="2"> </td> </tr> </tbody> </table>	Lights		We have turned on & off the head lights, blinkers, hazard lights, and interior dome lights on vehicle		<i>No issues noted</i>	<i>See Comments</i>	X		<i>Comments:</i>				<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th colspan="2" style="text-align: center;">Glass</th> </tr> </thead> <tbody> <tr> <td colspan="2">We have inspected all glass on vehicle for chips, cracks, tint, and general condition issues.</td> </tr> <tr> <td style="text-align: center;"><i>No issues noted</i></td> <td style="text-align: center;"><i>See Comments</i></td> </tr> <tr> <td style="text-align: center;">X</td> <td></td> </tr> <tr> <td colspan="2"><i>Comments:</i></td> </tr> <tr> <td colspan="2"> </td> </tr> </tbody> </table>	Glass		We have inspected all glass on vehicle for chips, cracks, tint, and general condition issues.		<i>No issues noted</i>	<i>See Comments</i>	X		<i>Comments:</i>					
Brakes and Suspension																																								
We have driven the vehicle around the yard three times stopping and going and listened for noises.																																								
<i>No issues noted</i>	<i>See Comments</i>																																							
X																																								
<i>Comments:</i>																																								
Lights																																								
We have turned on & off the head lights, blinkers, hazard lights, and interior dome lights on vehicle																																								
<i>No issues noted</i>	<i>See Comments</i>																																							
X																																								
<i>Comments:</i>																																								
Glass																																								
We have inspected all glass on vehicle for chips, cracks, tint, and general condition issues.																																								
<i>No issues noted</i>	<i>See Comments</i>																																							
X																																								
<i>Comments:</i>																																								

